

## Equipment and supplies required for the Face Shield

### Equipment

1. 3D printer with a print bed of minimum 7 x7 inches
2. Hot glue gun
3. Sharp cutting tool
4. Screwdriver
5. Drill with 3/16 inch bit
6. Tape measure or ruler
7. Scissors
8. Wood cutting surface

### Material

1. PLA filament for the 3D printer
2. Hot glue sticks
3. Masking tape
4. Foam tape (Frost King 3/8 in x 7/16 x 10 feet Black High-density foam weatherstrip tape - Home Depot)
5. Velcro 1/2 inch wide with self stick backing (Home Depot)
6. 8.5 by 11 inch clear-gloss poly binding cover (Office Depot item 459-307)
7. Rubber strips(used bicycle inner tube cut into strips)